

HOW TO ORDER

XC400/600

X C - A B C D E

A	B	C	D	E
Power supply	Measurement unit	Buzzer	4÷20mA	PWM
0 = 12Vac/dc 1 = 24Vac/dc 2 = 24Vac 4 = 110Vac 5 = 230Vac	C = °C F = °F B = Bar P = PSI	0 = No 1 = Yes	0 No 1 No 2 Yes 3 Yes	No Yes No Yes
				Inputs A = PP11 B = PP30 C = NTC D = PTC E = 4÷20mA F = Suction PP11; Condenser PP30