

HOW TO ORDER

XC200L

X C 2 6 L - A B C D 0

A	B	C	D
Power supply	Measurement unit	RTC	Buzzer
0 = 12Vac/dc 1 = 24Vac/dc	0 = °C/bar 1 = °F/PSI 2 = °C/Kpa	0 = No 1 = Yes	0 = No 1 = Yes