

HOW TO ORDER

XCM

X C M - A B O D E

A	B	D	E
Power supply	Input	Measurement unit	Extended memory for infrared
2 = 24Vac 4 = 110Vac 5 = 230Vac	A = Suction PP07; Condensing PP30 B = Suction PP07; Condensing NTC C = Suction NTC; Condensing PP30 D = Suction PP11; Condensing NTC E = Suction PP11; Condensing PP30 N = NTC	1 = Bar - °C 2 = PSI - °F 3 = KPA - °C	0 = No 1 = Yes