

X	R	4			C	-	A	B	C	D	0
---	---	---	--	--	---	---	---	---	---	---	---

-17.8

A	B	C	D
Power supply	Buzzer	RTC	Measurement unit
0 = 12Vac/dc 1 = 24Vac/dc 2 = 24Vac 4 = 110Vac 5 = 230Vac	0 = No 1 = Yes	0 = No 1 = Yes	C = °C F = °F

X	W	4				-	A	B	C	D	0
---	---	---	--	--	--	---	---	---	---	---	---



-17.8

Downloaded from <http://ajph.org/> on November 10, 2015

A	B	C	D
Power supply	Buzzer	RTC	Measurement unit
2 = 24Vac 4 = 110Vac 5 = 230Vac	0 = No 1 = Yes	0 = No 1 = Yes	C = °C F = °F